

## Erratum to: Inhibition of Pitting Corrosion Failure of Copper Tubes in Wet Sprinkler Systems

Sang Hee Suh<sup>1,†</sup>, Youngjoon Suh<sup>1</sup>, Jonghyuk Lee<sup>1</sup>, and HyukSang Kwon<sup>2</sup>

<sup>1</sup>Suh and Suh Corrosion Engineering, Daewangpangyo-ro 606-gil 31, Bundang-gu, Gyeonggi-do 13524, Republic of Korea

<sup>2</sup>Dept. of Materials Science & Eng., KAIST, 291 Daehak-ro, Yuseong-gu, Daejeon 34141, Republic of Korea

Erratum to: CORROSION SCIENCE AND TECHNOLOGY, Vol. 19, No. 2(2020), pp. 89~99  
DOI: <https://doi.org/10.14773/cst.2020.19.2.89>

### Correction

p. 94

- right 40 line; change 'Fig. 10에 부식방지 작업 1년 전인' to 'Fig. 10에 부식방지 작업 14개월 전인'

p. 95

- left 15 ~ 17 line; change 'Fig. 11은 부식방지 작업 전 1년 동안과 부식방지 작업 후 2019년 1년 동안의 누수 횟수를 비교하여 보여준다.' to 'Fig. 11은 부식방지 작업 전 14개월 동안과 부식방지 작업 후 2019년 1월부터 14개월 동안의 월평균 누수횟수를 비교하여 보여준다.'

p. 95

- right 9 ~ 10 line; change '이에 따라 2019년도의 1년간 누수횟수는 11회로 일년 전 62회의 18%로 크게 줄어들었다.' to '이에 따라 Fig. 11에서 부식방지작업 후의 월평균 누수횟수는 부식방지작업 전 4.43회에서 81% 감소한 0.86회로 크게 줄어들었다.'

p. 96

- left Fig. 11; Change 'Fig. 11 Yearly leakage number of times before and after BTAH corrosion inhibition work.' to 'Fig. 11 Average monthly leakage number before and after BTAH corrosion inhibition work.'




Fig. 11 Yearly leakage number of times before and after BTAH corrosion inhibition work.




Fig. 11 Average monthly leakage number before and after BTAH corrosion inhibition work.

p. 98

- right 5 ~ 6 line; Change '(3) BATH 수용액을 충수하는 방법은 연간 누수횟수를 82% 이상 감소시켜' to '(4) BATH 수용액을 충수하는 방법은 월평균 누수횟수를 81% 감소시켜'
- right 11 line; Change '(4) 스프링클러' to '(5) 스프링클러'
- right 21 line; Change '(5) BATH 수용액을' to '(6) BATH 수용액을'